

## Roosevelt Water Association Inc.

PO Box 345  
Snohomish, WA. 98291-0345  
360.568.3450 Fax 360.568.5369  
www.RooseveltWater.com



---

### April 2014 1<sup>st</sup> Quarter Manager Report

January brought a few cold days and we had a few frozen meters. Shavings were placed in the boxes and lids were secured. In March we had a broken water main along Hwy 2 between Roosevelt Road and Westwick, the calls from the customers reporting the outage and low water pressure made my job of locating the break much easier. Thank you. We are continuing to get customer information so we can contact and place you on the alert list for these types of problems, if you have not received the Member Certificate and Emergency Contact list please e-mail or phone so we can mail you both. You can also go to our website and sign up. [www.rooseveltwater.com](http://www.rooseveltwater.com).

April 8<sup>th</sup> we began flushing the water lines in Lupine. If you notice air or discolored water and it does not seem to go away after a couple days, please contact us.

On Trombley Road between 105<sup>th</sup> and 109<sup>th</sup> the County is replacing a piece of the road which is sinking. Roosevelt's water main is on the North/West side of the road and is in the way of this project. We will be moving the water main to the other side of the road beginning April 9<sup>th</sup>. Following this the County will be doing the road repair. We will be flushing Trombley Road at the completion of our pipe replacement which will be around April 18<sup>th</sup>. This will be posted on our website. We will continue to flush the remainder of our water system and will post the locations.

We have begun taking credit/debit card payments. The link for this secured payment option is on the website.

The 2013 Water Quality Report has been posted on the website, if you desire a printed copy we will mail one upon your request.

We are continuing to replace the manual water meters with the radio meters and are currently doing this in the Robinhood Park area.

Reminder to have your sprinkler backflow inspected.

Cross-connections that could contaminate drinking water distribution lines are a major concern. A cross-connection is formed at any point where a drinking water line connects to equipment. The Roosevelt Water Association requires those connections to be tested each year in the spring. It is required by Washington State Health Department to have your Sprinkler system inspected each year. Your inspection company will report this to RWA each year.

For more information please go to

Janelle MacDicken Manager Roosevelt Water Association